



## State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection:			
OGM	Karl Houskeeper		

# **Inspection Report**

Permit Number:	C0150007		
Inspection Type:	PARTIAL		
Inspection Date:	Monday, November 26, 2012		
Start Date/Time:	11/26/2012 8:00:00 AM		
End Date/Time:	11/26/2012 11:00:00 AM		
Last Inspection:	Wednesday, October 24, 2012		

Inspector: Karl Houskeeper,

Weather: <u>Clear Skies, Temp. 30 Deg. F.</u> InspectionID Report Number: <u>3306</u>

Accepted by: jhelfric 11/29/2012

Permitee: CONSOLIDATION COAL CO
Operator: CONSOLIDATION COAL CO
Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

**Current Acreages** 

0 Total Permitted	960.00
0 Total Disturbed	6.70
0 Phase I	6.70
Phase II	
Phase III	

Mineral Ownership

Federal

Types of Operations

✓ Underground

 State
 Surface

 County
 Loadout

 ✓ Fee
 Processing

 Other
 Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Checked in at the main office located at the Emery Deep Mine before proceeding on the Partial Inspection of the Hidden Valley Mine.

-Karl R. Houskeeper

Inspector's Signature:

Date

Monday, Novem



Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Monday, November 26, 2012

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
   For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
   For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>V</b>		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.2	Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

**Inspection Continuation Sheet** 

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Monday, November 26, 2012

Page 3 of 3

### 2. Signs and Markers

The mine identification sign is located at the end of the county road used to access the mine site. The sign contained the required information.

### 4.c Hydrologic Balance: Other Sediment Control Measures

The silt fence that is located adjacent to the mine identification sign was inspected and found to be functional.